





## **DRONE INSPECTION REPORT**

06/06/2018

## PROPERTY INFORMATION

**JOB NAME** 

Catholic Church

JOB TYPE
Commercial
PHONE NUMBER
N/A
EMAIL ADDRESS
N/A



#### FLIGHT INFORMATION




PHOTO LOCATIONS FROM SCAN

## **ABOUT THIS REPORT**

TOTAL IMAGES IN REPORT DATE REPORT CREATED 21 06/21/2018

PAGE#

TOTAL NUMBER OF ANNOTATIONS 20

3


PILOT IN COMMAND Jed Beck

DRONE ID NUMBER TOTAL FLIGHT TIME

07JDDBA00101NL 00:13:50

START TIME END TIME

16:14 EDT -0400 16:28 EDT -0400



## DC002-1 HAIL





Annotated by Jed Beck on 06/06/2018 16:44 EDT -0400

#### **Additional Notes**

Jed 06/06/2018 16:44 EDT -0400 Beck

Hail damage to this surface.

## DC002-2 WATER





Annotated by Jed Beck on 06/07/2018 12:09 EDT -0400

## **Additional Notes**

Jed 06/07/2018 12:09 EDT -0400 Beck

Wear on shingles.

## DC002-3 HAIL





Annotated by Jed Beck on 06/11/2018 18:15 EDT -0400

#### **Additional Notes**

# DC002-4 HAIL





Annotated by Jed Beck on 06/11/2018 18:34 EDT -0400

## **Additional Notes**

#### PO002-1 OTHER





Annotated by Jed Beck on 06/06/2018 18:41 EDT -0400

#### **Additional Notes**

Jed 06/06/2018 18:41 EDT -0400 Beck

Damage to roof.

## PO002-2 WATER





Annotated by Jed Beck on 06/07/2018 12:10 EDT -0400

#### **Additional Notes**

Jed 06/07/2018 12:10 EDT -0400 Beck

Wear on shingles.

## **PO002-3 WIND**





Annotated by Jed Beck on 06/07/2018 12:10 EDT -0400

#### **Additional Notes**

Jed 06/07/2018 12:10 EDT -0400 Beck Damage to shingle.

## PO002-4 OTHER





Annotated by Jed Beck on 06/07/2018 12:11 EDT -0400

## **Additional Notes**

## PO003-1 WATER






Annotated by Jed Beck on 06/07/2018 12:06 EDT -0400

## **Additional Notes**

Jed 06/07/2018 12:06 EDT -0400 Beck

Copper caps

# PO003-2 WIND





Annotated by Jed Beck on 06/07/2018 12:07 EDT -0400

## **Additional Notes**

Jed 06/07/2018 12:07 EDT -0400 Beck

Missing Shingles

#### **PO003-3 WIND**





Annotated by Jed Beck on 06/07/2018 12:07 EDT -0400

#### **Additional Notes**

Jed 06/07/2018 12:07 EDT -0400 Beck Shingles in valley.

## DC001-1 WIND






Annotated by Jed Beck on 06/07/2018 12:08 EDT -0400

#### **Additional Notes**

Jed 06/07/2018 12:08 EDT -0400 Beck Shingle falling.

## DC001-2 WATER





Annotated by Jed Beck on 06/07/2018 12:08 EDT -0400

#### **Additional Notes**

Jed 06/07/2018 12:08 EDT -0400 Beck

Wear on shingles.

# DC001-3 WIND





Annotated by Jed Beck on 06/11/2018 17:50 EDT -0400

## **Additional Notes**

Jed 06/11/2018 17:50 EDT -0400 Beck

Wind damage.

#### DC001-4 WIND





Annotated by Jed Beck on 06/11/2018 17:59 EDT -0400

#### **Additional Notes**

Jed 06/11/2018 17:59 EDT -0400 Beck

Wind damage to roof.

# DC001-5 WIND





Annotated by Jed Beck on 06/21/2018 14:09 EDT -0400

#### **Additional Notes**

Jed 06/21/2018 14:09 EDT -0400 Beck

Issue with shingle.

## PO001-1 WATER






Annotated by Jed Beck on 06/07/2018 12:09 EDT -0400

#### **Additional Notes**

Jed 06/07/2018 12:09 EDT -0400 Beck

Wear on shingles.

## PO004-1 WIND





Annotated by Jed Beck on 06/07/2018 12:11 EDT -0400

## **Additional Notes**

Jed 06/07/2018 12:11 EDT -0400 Beck

Missing shingle.

#### PO004-2 OTHER





Annotated by Nigel Parfitt on 06/07/2018 12:46 EDT -0400

#### **Additional Notes**

Nigel 06/07/2018 12:46 EDT -0400 Parfitt Missing Shingles

## LM088-1 OTHER





Annotated by Jed Beck on 06/07/2018 12:13 EDT -0400

#### **Additional Notes**

Jed 06/07/2018 12:13 EDT -0400 Beck Side view of Chapel.